FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re. G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

1. Na	me of the Officer	VARUCHESE CAPEN, ASST EXE CHAINEER
2. Nar	ne of the School	SREE GOKULAM PUBLIC SCHOOL PAZHUVIL CO
3. Loc	ation with name of Education District/ Sub. District	THRISSUR THRISSUR
4 Clas	ssification of Building as specified in column 4 of the lication for fitness certificate and size.	Rcc Framed Structure Building Pluoth Area UF - 1594.32 m² FF - 1335.96 m²
		SF - 1314 . 66 m
5. Peri	od for which the certificate is issued	TF - 1273.92 m
	ure of defects , if any	57AIR ROOM- 68.95 m2
a) Fo	oundation and basement '	MACHINE ROOM-23.43 m2
b) Si	uperstructure	Total 5611.24 m2.
c) De	oors and Windows	
d) W	/ood work wrought and put up	
e) R	oof	
f) Flo	poring	
g) M	iscellaneous (Cracks, etc.)	
7. Any build	major defects noticed which will render the ing unsafe in any manner	No
8. Whe	ther maintenance works have been done properly	yes.
Note exp	ther the structure is sound or not for conducting classes: 1. The stability of the structure should be examined also posure of flood etc. 2. Any additional observations if deer arately with this certificate.	Birilding is Sound for conducting classes on norm weather condition with reference to location, altitude, intensity of wind, med necessary for the certificate may be furnished
	CERTIFIC	ATE 7
0	pertified that the school building was inspected by me o	n 19-03-2021 and
	pe fit / unfit to conduct classes, for the period	

Place Peringotulcara

Date: 08-04-2021

reasons stated above.



Harryhead

Assistant Engineer
Assistant Executive Engineer
LSGD. Sub Division

Scanned with CamScanner

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer) (Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 - 1970)

1. Name of the Officer	1.	Name	of	the Officer
------------------------	----	------	----	-------------

- Name of the School
- Location with name of Education District/ Sub. District
- Classification of Building as specified in column 4 of the application for fitness certificate and size.

7	Period f	or which	the cert	lificate	is issued	i

- Nature of defects, if any
 - a) Foundation and basement
 - b) Superstructure
 - c) Doors and Windows
 - d) Wood work wrought and put up
 - e) Roof
 - f) Flooring
 - g) Miscellaneous (Cracks, etc.)
- Any major defects noticed which will render the building unsafe in any manner
- Whether maintenance works have been done properly

Whether the structure is sound or not for conducting classes

Building 13 Sound for conducting classes in normal tweather conditions.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the vertificate may be furnished separately with this certificate.

separately with this certificate.

CERTIFICATE

NIY.

certified that the so	chool building was inspected by	me on 19 03 2021	and
found to be fit / unfit to con-	duct classes, for the period	2021-2022 (up to 31-03.	2022) for the
reasons stated above.	15		

Place Peringettulcara 08-04-2021



Assistant Executive Engineer L3GD. Sub Division ANTHIKAD BLOCK PANCHAYATH P.O. Kizhakkumuri, Thrissur.

VARUGHESE CAPEN, ASST EXE ENGINEER SREE GOKULAM PUBLIC SCHOOL PAZHUVIL (W)

Rcc Framed Structure Building

6F- 1594.32 m

FF - 1335.96 m2 SF - 1314 . 66 HZ TF - 1273.92 m2 51AIR ROOM- 68.95 m2

MACHINE ROOM - 23-43 m2

90-1al 5611.24 m2

THRISSUA.

Pluoth Area.

THRISSUR.

Scanned with CamScanner

SREE GOKULAM SCHOOL PAZHUVIL WEST

CLASS ROOM DTAILS

CLA	ASS ROOM DTAIL
Ground Floor	
Classroom (5)	625x625
Chemistry Lab (1)	1271x625
Lab (1)	625x948
Physics Lab (1)	745x1917
Dining (1)	618X625
Store	948x625
Office	625x1474
Chairman room	625x625
Visitors room	625x625
Principal room	396x625
Staff room	625x302
<u>First floor</u>	
Senior computer Lab	1271x625
Audio visual room	618x625
Class room(3)	625x948
Class room4	625x625
Class room(1).	625x828
Class room(1)	618 x625
Class room(1)	625x745
Class room(2)	625x302
Visitors room(1)	625x625
Biology room (1)	625x1271
Second floor	
Class room(5)	625x625
Library(1)	1246x625
Class room(2)	948x625
Class room(3)	640x625
Class room(1)	640x828
Class room(1)	618x640
Class room(1)	760x525
Staff room(1)	640x302
Staff room(1)	625x302
Counseling room (1)	625x302
Vice principal room(1)	302x640
I spiroun(i)	23211010

Third floor	
Class room(8)	625x625
Class room(1)	618x625
Class room(2)	640x625
Class room(1)	640x828
Class room(1)	948x640
Class room(1)	618x640
Class room(1)	760x625
Room	302x605
Room	760x302
Staff room	640x302
Staff room	625x302
Visitors room	625x640
HM room	625x301



Assistant Executive Engineer
Assistant Executive Engineer
LSGD. Sub Division
ANTHIKAD BLOCK PANCHAYATH
P.O. Kizhakkumuri, Thrissur.